

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1 BRS	1302	digital adj multimeter\$1	USPAT; US-PGPUB; EPO; 2004/06/08 JPO; DERWENT; IBM_TDB	2004/06/08 12:45		
2 BRS	3	digital adj multimeter\$1 adj adapter\$1	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:16		
3 BRS	70	digital adj adapter\$1	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:25		
4 IS&R	4	("4034291").PN.	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:25		
5 BRS	7	digital adj multimeter\$1 and interface with processor with memory with display\$3	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:33		
6 BRS	1	digital adj multimeter\$1 with portable and interface with processor with memory with display\$3	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:34		

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
7	BRS	2	digital adj multimeter\$1 with portable and processor with memory with display\$3	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:34		
8	BRS	26	digital adj multimeter\$1 with portable	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:38		
9	BRS	6	digital adj multimeter\$1 with portable and waveform\$1	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:35		
10	BRS	11	4034291.uref.	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:35		
11	BRS	45	digital adj multimeter\$1 with (hand-held or portable)	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:38		
12	BRS	8	digital adj multimeter\$1 with (hand-held or portable) and waveform\$1	USPAT; US-PGPUB; EPO; 2004/06/07 JPO; DERWENT; IBM_TDB	2004/06/07 15:55		

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
13	IS&R	2	("5876351").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/07 15:55		
14	IS&R	2	("5923161").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 10:00		
15	BRS	1498	702/57,64,65,66,67,68,70.c cls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 13:14		
16	BRS	2570	324/76.11,76.12,76.15,115, 375.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 10:16		
17	BRS	2934	324/76.11,76.12,76.15,111, 115,375.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 10:16		
18	BRS	4040	324/76.11,76.12,76.15,111, 121r,115,375.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 10:16		

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definiti on
19 BRS	11	(digital adj multimeter\$1 or DMM) with adapter	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 13:47		
20 BRS	1841	702/57,64,65,66,67,68,70,1 24.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 13:14		
21 BRS	61	(digital adj multimeter\$1 or DMM) and ((graphical adj user adj interface) or gui)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 13:49		
22 BRS	32	(digital adj multimeter\$1) and ((graphical adj user adj interface) or gui)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 14:40		
23 IS&R	2	("6292717").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 14:35		
24 BRS	33	(digital adj multimeter\$1) and display\$3 with text	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 14:41		